

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

TOWATH ALCOHOL PROTRAY:

DATAMASTER MAINTENANCE REPORT

Complete this report in duplicate at the time of the regular is repaired. Send copy to Department of Health; retain original to the complete this report in duplicate at the time of the regular transfer in the complete this report in duplicate at the time of the regular transfer in the complete this report in duplicate at the time of the regular transfer in the complete this report in duplicate at the time of the regular transfer in the complete this report in duplicate at the time of the regular transfer in the complete this report in duplicate at the time of the regular transfer in the complete this report in duplicate at the time of the regular transfer in the complete this report in the com	ular monthly preventive maintenance check, and whenever instrument ginal in department file.		
DATAMASTER SN	DG /01/09		
TROOP B 20NE 6, 204078 LOCATION OF INSTRUMENT (STREET AND CITY)	TIME OF INSPECTION		
518 N LINCOLN ST. KAHOKA	1445		
CHECKLIST: Place a check (✓) to the left of each item if in observed values where determined.) Unchecked items m	found to be satisfactory or if operating within established limits. (Write nust be corrected before using instrument.		
DIAGNOSTIC CHECK (PRINTOUT ATTACHED)			
☑ COMPUTER	DETECTOR		
☑ PROGRAM	M FILTERS		
☐ HEATERS SAMPLE CHAMBER 49 °C	☑ QUARTZ STANDARD		
FLOW DETECTOR	☑ CALIBRATION		
☑ PUMP HIGH SPEED	PRINTER		
1 INDICATOR LIGHTS			
☑ TIME AND DATE			
SIMULATOR TEMPERATURE (34 °C ± 0.2°C) 34.1°C			
CALIBRATION CHECK - WITHIN SPECIFICATIONS			
Run three tests using a standard solution. All three tests must be within + 5% of the standard value and must have a			
spread of .005 or less. Check the box corresponding RECIRCULATION PUMP)	to the standard solution being used. (PRINTOUT ATTACHED) (USE		
0.100% STANDARD - MUST READ BETWEEN 0.09	95% and 0.105% INCLUSIVE		
0.040% STANDARD - MUST READ BETWEEN 0.03 (ONLY ONE STANDARD IS TO BE USED PER MAIN)			
TEST 1 . 098 TEST 2	.098 TEST 3 F .099		
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)			
NUMBER OF REFUSALS, SINCE LAST MAINTENANC	CE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS		
FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS			
REFUSALS (004) (.0509)) (.1014) 2 (.1519) / (Over .19) /		
List any new parts and describe any alteration or modific and within established limits (use other side if necessary)	cation that was made to restore the instrument to operate satisfactorily		
GUYH LABORATORIES TNC. L	UT # 08340		
EXP: 10/15/09 VAPOR CONCENTRATION: 0/0			
LAT. 1110707 VIII CONCENTRAL CONCENTRAL			
INSPECTING OFFICER			
SIGNATURE JD Davidson	PRINT NAME JOSEPH D. DAVIDSON		
TYPE II PERMIT NUMBER/EXPIRATION DATE 820324 / 12-10 -10	TELEPHONE NUMBER 660 -385- 2132		



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 08340 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1211 percent (w/vol) ethyl alcohol. The expiration date for this lot number is October 15, 2009 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and we r used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL MUMBER 204075 06/01/09

TESTIMS OFFICER:
DAVIDSON/JOSEPH/D
OFFICER I.D.: 191
PERMIT NUMBER: 820884
EXPIRATION DATE: 12/18/10
MISCELLAMEOUS DATA:
.10 MAINT.

-- SUPERVISOR MODE ---

BLANK TEST	. Mád	1. 4. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
INTERNAL STANDARD	VERTF16D	164550
EXTERNAL STANDARD	. 598	$(\frac{1}{2}, \frac{1}{2}, $
BLRIK TEST	. 665	14457
EXTERMAL STANDARD	. 890	14457
BLANK TEST	, yes	14:58
EXTERMAL CTAMBERD	.089	美华美丽岩.
ALAMO TEST	. 24Hb	14459

|h = 3 |-01/1. = .1 |AV6. = .0983 Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL HUMBER 204078 06/01/09

ANKEST TIME: 14:48
SUBJECT MAME:
TESTURFI
DOB: 61/61/98 SEX: F
STATE/D.L.: MAVMA
ARRESTIMG OFFICER:
DAVIDSOM/JOSEPH/D
OFFICER I.D.: 191
TESTIMG OFFICER:
DAVIDSOM/JOSEPH/D
OFFICER I.D.: 191
PERMI! MUMBER: 68:324
EXPIRATION DATE: 12/18/18
MISCELLAMEOUS DATH:
RFI TEST

--- XKEATH AMALYSIS ---

RLABK TEST INTERNAL STANDARU RADIO INTERFERENCE .000 15:02 VERIFIED 15:02

Operator Signature IPR JD Davidson

Printed on recycled paper with agri-based inks

CMSU 2 .

Operator Signature (PR) D =

Printed on recycled paper with agri-based inks

CMSU 2208-02

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204079 06/01/09 14:45

--- DIAGNOSTIC CHECK ----

COMPUTER

OKRY

PROGRAMA

OKBY

HEATERS

SAMPLE, CHAMBER:

490

FLOW DETECTOR:

OKMY

PLHP

HIGH SPEED:

UKAY

DETECTORS

QKHY

FILTERSS

ORRY

BURRTZ STARDARD:

CIRCHY

CALIBRATION:

OKAY

PRINTER TEXT

!"#\$%&(()*+.-./6123456789#:<=>?@A&CDEF0 HIUKLMMOPGRSTUVWXYZE\l^__'abcdetghijklomo pqrstuvwxyz{}}+"

Operator Signature

Printed on recycled paper with agri-based inks

CMSU 2208-02

State of Missouri DEPARTMENT OF HEALTH



PERMIT TYPE II



JOSEPH D DAVIDSON

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

$ \begin{array}{c} 12/10/08 \\ \hline $	12/10/08	John of Mathewson
		Director of State Dublic Health Laboratory
	Control Control	
Expires		- Director, Department of Health
MO 580-0771 (7-88)		Lab. 4 (A7-86